


KIA Sportage Bj. 1995-

Art.Nr. 11.0306







- 5. Fix element "2" to the radiator bam with bolts M 8x20-(D).
- 6. Fix both elements to the fastening plate with bolts M 10x20-(E).
- 7. Tighten all screw joints.

